extends your EnOcean by a new dimension

Known Bugs

by

BootUp *GmbH*

Pending Bugs

Problem:	Weatherstation WMR918/WMR928		
Entry:	2010.03.12	Fix:	V1.2.4
Id:	2010.02.12.1		
Statement:	1. myHomeControl doesn't drive the RTS signal of the RS232. Therefore a NULL modem has to be used to enable the weather station to send data to the PC. 2. The "new THB message" sent by new out side temperature sensor is not evaluated.		
Workaround:	use a NULL-Modem		

Problem:	Sequence block		
Entry:	2010.02.08	Fix:	V1.2.4
Id:	2010.02.08.1		
Statement:	The sequence block doesn't react on the up/down commands.		
Workaround:	none		

Solved Bugs

Problem:	USB Camera		
Entry:	2009.11.17	Fix:	V1.2.1
Id:	2009.11.17.1		
Statement:	The first camera listed in the list of local cameras is not operational-		
Workaround:	none		

Problem:	Properties dialog of the PIR block, missing close button		
Entry:	2009.09.14	Fix:	V12 28.09.2009
Id:	2009.09.14.1		
Statement:	In some cases the close button is missing in the properties dialog of the PIR blocks (red button with white cross).		
Workaround:	Open a properties dialog of an other block.		

Problem:	Exception in Visualization Element PTM Button		
Entry:	2009.09.01	Fix:	V1.2 28.09.2009
Id:	2009.09.01.1		
Statement:	Appearance "Dialog with buttons": In case the symbol has been clicked to open the control dialog an exception appears.		
Workaround:	Select the appearance "Buttons".		

Problem:	**disconnect USB-Converter**		
Entry:	2009.08.26	Fix:	V1.2 Beta 28.08.2009
Id:	2009.08.26.1		

Statement: In case a USB-Converter (USB<->RS232 or USB<->RS485) gets removed from the USB port, then myHomeControl hangs-up.

Problem:	**Single button control (toggle mode)**		
Entry:	2009.08.25	Fix:	V1.2 Beta 28.08.2009
Id:	2009.08.25.3		
Statement:	A switching actuator shall be controlled by a single button of a rocker switch. Therefore a toggle block is used. In case the switching actuator has been operated directly on the screen, then the toggle block looses synchronization.		

Problem:	**Blind actuator from PEHA / Scenes**		
Entry:	2009.08.25	Fix:	V1.2 Beta 28.08.2009
Id:	2009.08.25.2		
Statement:	The blind actuator does not drive the blind to the position stored in a scene.		

Problem:	**Blind actuator from PEHA**		
Entry:	2009.08.25	Fix:	V1.2 Beta 28.08.2009
Id:	2009.08.25.1		
Statement:	The blind actuator does not automatically drive to the end position in case the button in myHomeControl has been pressed for long time.		

Problem:	**Thermokon EasySens Gateway**		
Entry:	2009.08.20	Fix:	V1.2 Beta 20.08.2009
Id:	2009.08.20.1		
Statement:	**myHomeControl®** is not able to access the Ethernet-Gateway from Thermokon.		